

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/29/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/17/12 – 0700, 05/31/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
09:00	<p>Overflight Operational status:</p> <ul style="list-style-type: none"> <li>• Source area pond, no sheen observed.</li> <li>• Frac-Tank City decon pad and soil cells. Boat observed in decon area.</li> <li>• Frac-Tank City, footprint reduction continues.</li> <li>• Confluence, no turbidity or sheen observed.</li> <li>• Observed public utilizing Saylor's Landing.</li> <li>• MP4.5 LDB, no sheen observed.</li> <li>• Above Ceresco Dam, sheen observed.</li> <li>• Control point above Ceresco Dam, some debris observed within containment.</li> <li>• MP10.75, sheen observed within boom.</li> <li>• MP13.0, land owner mowed field.</li> <li>• MP15.75 Mill Ponds culverts, sheen observed within containment.</li> <li>• MP21.5, no sheen observed within boom.</li> <li>• MP26.0 RDB, sheen observed.</li> <li>• MP26.25 RDB, sheen observed.</li> <li>• MP 28.25 oxbow, sheen observed within oxbow.</li> <li>• MP30.8 LDB, no sheen observed.</li> <li>• Morrow Lake Delta, sheen observed around sandbar.</li> <li>• Control Point E4, no sheen observed.</li> <li>• No activity observed below Morrow Lake Dam.</li> </ul>		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			